

## Swimming Pool / Spa Safety Barrier Inspection Report

Address Inspected:

55 Townsing Road, KARDINYA WA 6163

Inspection Date: 28-Mar-2025

Inspection Time: 3:30 PM

Inspector: Jaymee Goddard

Type of Pool

**Pool Construction** 

**Pool Position** 

Home Owner / Occupier present at time of

inspection?

**Rental Contact** 

Contact Number:

**Email Address:** 

Lic No: 11518-SP4

Inspectors Contact: 0466 025 976

Pool

Below Ground - Fibreglass

Yes

Inspection Result:

COMPLIANT

An authorised officer of the Council has visited your property and inspected the swimming pool / spa barrier. The fences and gates comply with the Building Act 2011, Building Regulations 2012 (As Amended), and Australian Standard 1926.1-1993 and 1926.1-2012.

Important Note: It is the owners/occupiers obligation and responsibility to ensure that all swimming pool / spa safety barriers are maintained at all times

Comments: Barrier is boundary and isolation metal tubular with three (3) gates. Windows have security screen.

LHS gate safety cone hinge has been installed.

Black metal tubular gate is additional and does not have to comply.

Pool barrier complies.

Next Inspection Date: Within 4 years (from today's inspection date)

Delivery Method:E-mail

This document remains the property of the City of Melville and must not be used or relied upon by a

General Enquiries Tel: 1300 535 845 Fox: 08 9364 0285 www.meivillecity.com.au Street Address 10 Almondbury Road Booragoon WA 6154 Postal Address Locked Bag 1 Booragoon WA 6954