

Name & Address

S Smith, c/- Professionals Sandgate 73 BRIGHTON ROAD SANDGATE QLD 4017 AUSTRALIA 
 Report Number
 Client Reference

 W0-2271499
 13264

Inspection Address (Address where smoke alarms were inspected)

8/24 Sixteenth Avenue, Brighton, QLD 4017

Building Class Inspection Date

Class 1a 15/11/2021

Inspected By

Shane James

A tick in a box below indicates that on the Inspection Date and at the Inspection Address, the smoke alarms and smoke alarm installations were inspected and met the relevant requirements of the noted legislation.

cross in a box below indicates that on the Inspection Date and at the Inspection Address, the smoke alarms and smoke alarm installations were inspected and did not meet the relevant requirements of the noted legislation.



On the Inspection Date and at the Inspection Address the smoke alarms met the Current Requirements.



On the Inspection Date and at the Inspection Address the smoke alarms met the New Requirements.

#### **SMOKE ALARMS**

At this inspection, the following alarms were present or installed.

VOLTAGE	TYPE	EXPIRES	LOCATION	ROOM	LEVEL	INSTALL REASON
10yr RF Interconn	PE	31/10/2031	Bedroom	1		Additional Required for Compliance
10yr RF Interconn	PE	31/10/2031	Bedroom	2		Additional Required for Compliance
240v RF Interconn	PE	31/07/2031	Hall			Additional Required for Compliance

#### COMMENTS

Removed existing alarms and installed alarms required to meet 2022 compliance.

## SAFETY SWITCH

The same of the sa			
RESULT	Sighted	LOCATION	Meter box right hand side
		The second secon	



## **IMPORTANT NOTES**

Build date means the date reasonably estimated by a Smoke Alarm Solutions technician to be the date on which the building at the Inspection

Class 1a building means a single dwelling property being — (i) a detached house; or (ii) one or more attached dwellings, each being a building, separated by a fire-resisting wall, reasonably estimated by a Smoke Alarm Solutions technician as such.

Class 2 building means a property containing 2 or more sole-occupancy units each being a separate dwelling, reasonably estimated by a Smoke Alarm Solutions technician as such.

Current Requirements means the legislative requirements stipulated by the Queensland Fire and Emergency Services Act 1990; Building Fire Safety Regulation 2008; and the Electrical Safety Act 2002 applicable to existent (pre-2022) smoke alarms and smoke alarm installations and related smoke alarm installations, build dates, including dates of significant renovations, and building classes.

New Requirements means the legislative requirements stipulated by the Queensland Fire and Emergency Services Act 1990; Building Fire Safety Regulation 2008; and the Electrical Safety Act 2002 to be in place by 1st January 2022 for rental properties and related electrical work (if applicable). Considerations around compliance of the smoke alarms at the Inspection Address are the types of smoke alarms and smoke alarm installations, build dates, including dates of significant renovations, and building classes.

### This is not a building compliance certificate.

Smoke Alarm Solutions is not a building certifier. Building compliance certificates relate to compliance with building plans and approvals granted by local, state and federal governments under various Building Acts and related construction and renovation requirements. Building certificates, and other types of certificates relating to construction and renovation safety (including automated fire suppression systems), issued by building certifiers, or other safety officials, refer to different points in time and different regulations. A building certificate issued at the end of construction, for example, may certify compliance with a building approval. The building approval may have been granted prior to a change in standards or regulations for smoke alarms and the installation of smoke alarms. The approval or the building certificate, or other such certificates, may have been granted or issued during a grace period allowed by legislation to ensure the orderly implementation of a new standard or regulation. A building compliance certificate, or other construction or renovation safety certificate, does not necessarily mean that the smoke alarms and smoke alarm installations are compliant with the standards and regulations for smoke alarms and smoke alarm installations in force in the State or Territory where the Inspection Address is situated. Similarly, a report indicating that the smoke alarms or smoke alarm installations are not compliant does not necessarily mean that a building compliance certificate, or other such certificate, is not valid. Please check with your building certifier or other safety officials with regard to the compliance requirements for your building or property, and the relevant dates, and exemptions or exceptions you may be entitled to under their governing laws and regulations.

#### **Qualified Compliance Report**

In certain instances there may be legislation that is current and in force, but stipulates the introduction of new compliance requirements. These requirements may be phased in over time and the legislation may allow a grace period or periods to facilitate the introduction of the new compliance requirements. Owing to changes in legislation (including legislation other than the various Building Acts) subsequent to the Build Date certain smoke alarms and smoke alarm installations already installed may become not required for compliance, and certain new smoke alarms and smoke alarm installations may become required for compliance. If a smoke alarm or smoke alarm installation is not required for compliance the property owner may remove the smoke alarm. If you choose to leave a not required for compliance smoke alarm installed you must ensure the smoke alarm is functional in accordance with current legislation. Smoke Alarm Solutions: (i) may service smoke alarms or smoke alarm installations that are not required for compliance, if those smoke alarm installations are not faulty and not expired; (ii) will remove smoke alarms and smoke alarm installations that are not required for compliance, if those smoke alarm installations are faulty or are expired; and (iii) does not replace smoke alarms and smoke alarm installations that are not required for compliance, if those smoke alarms or smoke alarm with a new compliant smoke alarm does not constitute a so-called 'replacement' and separate charges apply.

#### This is a smoke alarm compliance certificate

This report certifies compliance or non-compliance of the abovementioned smoke alarms and smoke alarm installations at the abovementioned Inspection Address with the abovementioned legislative requirements for smoke alarms and smoke alarm installations for the Building Class building in force on the Inspection Date in the State or Territory where the abovementioned Inspection Address is situated. If an electrical contractor license number appears on the face hereof, this report also certifies that insofar as the relevant smoke alarm installations and smoke alarms are electrical installations or electrical equipment and their installation, removal, repair, inspection or testing are electrical work as defined in the relevant legislation, at the Inspection Address and on the Inspection Date: (i) such electrical installation, to the extent that it is affected by the electrical work, has been tested to ensure it is electrically safe and is in accordance with the requirements of the wiring rules and any other standard applying to the electrical installation under the Current Requirements; and (ii) such electrical equipment, to the extent it is affected by the electrical work, is electrically safe in terms of the Current Requirements. Smoke Alarm Solutions is not a building surveyor, and does not know the relevant date that a property was built or renovated. Smoke Alarm Solutions' trained technicians use reasonable efforts to estimate the Building Class and, if relevant, the Build date and is not aware of any substantial, or other, renovation. If applicable, it is the property owner or its agent's responsibility to notify Smoke Alarm Solutions of the date when the property was built or substantially renovated and its classification.



Name & Address

S Smith, c/- Professionals Sandgate 73 BRIGHTON ROAD SANDGATE QLD 4017 AUSTRALIA 
 Report Number
 Client Reference

 W0-2271499
 13264

Inspection Address (Address where smoke alarms were inspected)

8/24 Sixteenth Avenue, Brighton, QLD 4017

Building Class Inspection Date

Class 1a 15/11/2021

Inspected By

Shane James

A tick in a box below indicates that on the Inspection Date and at the Inspection Address, the smoke alarms and smoke alarm installations were inspected and met the relevant requirements of the noted legislation.

cross in a box below indicates that on the Inspection Date and at the Inspection Address, the smoke alarms and smoke alarm installations were inspected and did not meet the relevant requirements of the noted legislation.



On the Inspection Date and at the Inspection Address the smoke alarms met the Current Requirements.



On the Inspection Date and at the Inspection Address the smoke alarms met the New Requirements.

#### **SMOKE ALARMS**

At this inspection, the following alarms were present or installed.

VOLTAGE	TYPE	EXPIRES	LOCATION	ROOM	LEVEL	INSTALL REASON
10yr RF Interconn	PE	31/10/2031	Bedroom	1		Additional Required for Compliance
10yr RF Interconn	PE	31/10/2031	Bedroom	2		Additional Required for Compliance
240v RF Interconn	PE	31/07/2031	Hall			Additional Required for Compliance

#### COMMENTS

Removed existing alarms and installed alarms required to meet 2022 compliance.

## SAFETY SWITCH

The same of the sa			
RESULT	Sighted	LOCATION	Meter box right hand side
		The second secon	



## **IMPORTANT NOTES**

Build date means the date reasonably estimated by a Smoke Alarm Solutions technician to be the date on which the building at the Inspection

Class 1a building means a single dwelling property being — (i) a detached house; or (ii) one or more attached dwellings, each being a building, separated by a fire-resisting wall, reasonably estimated by a Smoke Alarm Solutions technician as such.

Class 2 building means a property containing 2 or more sole-occupancy units each being a separate dwelling, reasonably estimated by a Smoke Alarm Solutions technician as such.

Current Requirements means the legislative requirements stipulated by the Queensland Fire and Emergency Services Act 1990; Building Fire Safety Regulation 2008; and the Electrical Safety Act 2002 applicable to existent (pre-2022) smoke alarms and smoke alarm installations and related smoke alarm installations, build dates, including dates of significant renovations, and building classes.

New Requirements means the legislative requirements stipulated by the Queensland Fire and Emergency Services Act 1990; Building Fire Safety Regulation 2008; and the Electrical Safety Act 2002 to be in place by 1st January 2022 for rental properties and related electrical work (if applicable). Considerations around compliance of the smoke alarms at the Inspection Address are the types of smoke alarms and smoke alarm installations, build dates, including dates of significant renovations, and building classes.

### This is not a building compliance certificate.

Smoke Alarm Solutions is not a building certifier. Building compliance certificates relate to compliance with building plans and approvals granted by local, state and federal governments under various Building Acts and related construction and renovation requirements. Building certificates, and other types of certificates relating to construction and renovation safety (including automated fire suppression systems), issued by building certifiers, or other safety officials, refer to different points in time and different regulations. A building certificate issued at the end of construction, for example, may certify compliance with a building approval. The building approval may have been granted prior to a change in standards or regulations for smoke alarms and the installation of smoke alarms. The approval or the building certificate, or other such certificates, may have been granted or issued during a grace period allowed by legislation to ensure the orderly implementation of a new standard or regulation. A building compliance certificate, or other construction or renovation safety certificate, does not necessarily mean that the smoke alarms and smoke alarm installations are compliant with the standards and regulations for smoke alarms and smoke alarm installations in force in the State or Territory where the Inspection Address is situated. Similarly, a report indicating that the smoke alarms or smoke alarm installations are not compliant does not necessarily mean that a building compliance certificate, or other such certificate, is not valid. Please check with your building certifier or other safety officials with regard to the compliance requirements for your building or property, and the relevant dates, and exemptions or exceptions you may be entitled to under their governing laws and regulations.

#### **Qualified Compliance Report**

In certain instances there may be legislation that is current and in force, but stipulates the introduction of new compliance requirements. These requirements may be phased in over time and the legislation may allow a grace period or periods to facilitate the introduction of the new compliance requirements. Owing to changes in legislation (including legislation other than the various Building Acts) subsequent to the Build Date certain smoke alarms and smoke alarm installations already installed may become not required for compliance, and certain new smoke alarms and smoke alarm installations may become required for compliance. If a smoke alarm or smoke alarm installation is not required for compliance the property owner may remove the smoke alarm. If you choose to leave a not required for compliance smoke alarm installed you must ensure the smoke alarm is functional in accordance with current legislation. Smoke Alarm Solutions: (i) may service smoke alarms or smoke alarm installations that are not required for compliance, if those smoke alarm installations are not faulty and not expired; (ii) will remove smoke alarms and smoke alarm installations that are not required for compliance, if those smoke alarm installations are faulty or are expired; and (iii) does not replace smoke alarms and smoke alarm installations that are not required for compliance, if those smoke alarms or smoke alarm with a new compliant smoke alarm does not constitute a so-called 'replacement' and separate charges apply.

#### This is a smoke alarm compliance certificate

This report certifies compliance or non-compliance of the abovementioned smoke alarms and smoke alarm installations at the abovementioned Inspection Address with the abovementioned legislative requirements for smoke alarms and smoke alarm installations for the Building Class building in force on the Inspection Date in the State or Territory where the abovementioned Inspection Address is situated. If an electrical contractor license number appears on the face hereof, this report also certifies that insofar as the relevant smoke alarm installations and smoke alarms are electrical installations or electrical equipment and their installation, removal, repair, inspection or testing are electrical work as defined in the relevant legislation, at the Inspection Address and on the Inspection Date: (i) such electrical installation, to the extent that it is affected by the electrical work, has been tested to ensure it is electrically safe and is in accordance with the requirements of the wiring rules and any other standard applying to the electrical installation under the Current Requirements; and (ii) such electrical equipment, to the extent it is affected by the electrical work, is electrically safe in terms of the Current Requirements. Smoke Alarm Solutions is not a building surveyor, and does not know the relevant date that a property was built or renovated. Smoke Alarm Solutions' trained technicians use reasonable efforts to estimate the Building Class and, if relevant, the Build date and is not aware of any substantial, or other, renovation. If applicable, it is the property owner or its agent's responsibility to notify Smoke Alarm Solutions of the date when the property was built or substantially renovated and its classification.



## WE DELIVER COMPLIANCE SOLUTIONS FOR PROPERTY MANAGERS AND LANDLORDS.

## **COMPLIANCE REPORT**

Owner	The Owner					
C/-	True Power Realty					
Address	59 Albany Creek Road, Aspley 4034					
	Bridgeman Downs		Postcode	4035		
Property Address	8 / 24 Sixteenth Aven	ue, Brighton 4017				
Date	17/07/2023 Monday		Report no.	52129		
Inspected By	Sam Maycock		Order no.	386a-152		
Services carried out	on this day					
Smoke Alarm Compli	iance	Safety Switch Test		Corded Wine	dow Furnishing	
Water Meter Reading		Methamphetamine S	creening			
Smoke Alarms						
On this date, this pro	perty complies with QL	D 2022 smoke alarm req	uirements			
n accordance with the Queen ime, this report will become in		e alarms at this property must	be re-inspected within	า 30 days prior to a lease	e renewal or tenancy change. A	t that
Comments						
Safety Switch Test						
Comments						
Corded Window Furn	nishings					
Water Meter Reading	1			Black	Red	
This property is covered	under an Annual Servi	ce Plan Until	01/08/2024			$\overline{}$

ELECTRICAL INSTALLATIONS (if completed by SAI) - We certify that the electrical installations, to the extent that it is affected by the electrical work, has been tested to ensure it is electrically safe and is in accordance with the requirements of the wiring rules and any other standard applying to the electrical installation under the Electrical Safety Regulations 2013.



# **SMOKE ALARMS PRESENT ON THIS DAY**

Property Address	8 / 24 Sixteenth Avenue, Brighton 4017				
		1			
Date	17/07/2023 Monday	Report no.	52129		
Inspected By	Sam Maycock	Order no.	386a-152		

Description	Location	Expiry	Required	I/C
10Yr PE Li RF Alarm - Other	Bed 1 (IC) EP	01/10/2031	Yes	Yes
10Yr PE Li RF Alarm - Other	Bed 2 (IC) EP	01/10/2031	Yes	Yes
240v PE Alarm 2014 - Other	EPB Hall (IC) EP + RFM	01/07/2031	Yes	Yes

INTEGRITY
IS DOING THE RIGHT
THING EVEN
WHEN NO ONE IS
WATCHING.



