

## **SMOKE ALARM COMPLIANCE REPORT**

Inspected By: Bailey Hamilton

Inspection Date: 29/10/24

## 38 Tea Trees Avenue, Springfield Lakes, QLD, 4300

| Smoke Alarms Present    | <b>Expiry Date</b> | Technology    | Brand      | Position  |
|-------------------------|--------------------|---------------|------------|-----------|
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Bed 1     |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Bed 2     |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Bed 3     |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Bed 4     |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Hallway 1 |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Hallway 2 |
| 10 Yr Li RF smoke alarm | Oct 2034           | Photoelectric | RED alarms | Hallway 3 |
|                         |                    |               |            |           |
|                         |                    |               |            |           |

Crusader Electrical Pty Ltd hereby certify that all smoke alarms installed at this property meet the requirements of the Building Code of Australia; Australia Standard As378;2014 and the Queensland Government smoke alarm regulations. The installation of the above-listed smoke alarms were installed according to the manufacturer's specifications. Crusader Electrical Pty Ltd, its employees and its directors will not be held responsible if any items have been tampered with, removed or damaged by the tenant/agent or any other party after our inspection.