

10th February 2025

Kirsty Lindner,
97-111 Wearing Road,
NORTH MACLEAN QLD

SMOKE ALARM CERTIFICATION

I, Steven Ryan being the licenced electrician and responsible installer, hereby certify that the smoke alarm/s located as follows:

MAIN HOUSE

Positions –

- 4x smoke alarms in bedrooms
- 1x smoke alarm in hallway
- All smoke alarms are 240V hardwired

GRANNY FLAT

Positions –

- 2 x smoke alarms in bedrooms
- 1 x smoke alarm in hallway
- All smoke alarms are 240V hardwired.

at 97-111 Wearing Road, North Maclean have been located, connected and installed in accordance with: - AS 3786 - 2014 - Smoke Alarms, - AS 3000 – 2007 – Electrical Installations, and - Part 3.7.2 of Volume 2 of the National Construction Code Series (BCA).

Maintaining Smoke Alarms

Smoke alarms should be regularly dusted or vacuumed to make sure they continue working properly.

Accidental alarms go off when there is no fire. They can be a nuisance and become dangerous if homeowners remove the alarm batteries or disable an interconnected system to silence the alarm.

The fire service is not permitted to disable sounding alarms in unattended residences.


Make sure you regularly:

- Test to ensure they are working correctly.
- Vacuum to ensure no dust affects the sensors.

Number of alarms: Eight (8)

Date of installation: 10th Febuary 2025

Company name: Rylec (Qld) Pty Ltd

Signature 

Licence number 77297