



# Service Report

## Smoke Alarm Safety Service

Ref #: SR6349450

Detector Inspector (QLD) Pty Ltd  
ABN 27 628 528 772  
www.detectorinspector.com.au

G+ in f y



Detector Inspector



### Property Address

3/129 Vernon Street , Nundah QLD 4012

Generated On: 12:43:58 13/07/2022



### Real Estate Agency

Image Property

Technician Name: Ivan Sionemale

Date Performed: 12/07/2022

Reference Number: 6349450

Supervisor: James (Lee) Muncey

Supervisor Licence No.: -



### Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:  
<https://detc.in/service-reports-5RTs5ypTNmBz3>

## Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

### Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Level 2)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

### Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Level 2)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

### Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #4 (Level Level 2)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

### Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Entrance #1 (Level Ground)

Compliant

Expiry Year: 2030  
Manufacturer: Detector Inspector

1 photo are available to view online

### Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Living Room #1 (Level Level 1)

Compliant

Expiry Year: 2030  
Manufacturer: Detector Inspector

1 photo are available to view online

### Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Hallway #1 (Level Level 2)

Compliant

Expiry Year: 2030  
Manufacturer: Detector Inspector

1 photo are available to view online

### Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Hallway #2 (Level Level 2)

Compliant

Expiry Year: 2030  
Manufacturer: Detector Inspector

1 photo are available to view online

### Switchboard (Smoke Alarm)

📍 Location/Position: Garage #1 (Level Ground)

Compliant

## Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

### Cord Guide

📍 Location/Position: Bedroom #2 (Level Level 2)

Compliant

Manufacturer: --Other--

1 photo are available to view online

