



Service Report

Smoke Alarm Safety Service

Ref #: SR6051581

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

17/22 Bridge Street , Nundah QLD 4012

Generated On: 17:29:22 25/02/2022

Technician Name: Mason Clarke (e)

Date Performed: 24/02/2022

Reference Number: 6051581



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-gFHqTUX0q3NnV>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Corridor #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Additional Notes

Since this is the only smoke alarm in the property that is required under the applicable legislation, no interconnection is required.

Mains 240 Volt 10Yr Lithium Smoke Alarm

Compliant

📍 Location/Position: Corridor #2 (Level Ground)

Expiry Year: 2031

Legislation
Check: 2

Manufacturer: Detector Inspector

1 photo are available to view online

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

Compliant

📍 Location/Position: Bedroom #1 (Level Ground)

1 photo are available to view online

Cord Guide

Compliant

📍 Location/Position: Bedroom #2 (Level Ground)

1 photo are available to view online

Cord Guide

Compliant

📍 Location/Position: Living Room #1 (Level Ground)

1 photo are available to view online