



Service Report

Smoke Alarm Safety Service

Ref #: SR6085276

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

73 Nightingale Street , Mount Gravatt East QLD 4122

Generated On: 16:00:02 12/04/2022

Technician Name: Olivia Mobbs

Date Performed: 09/04/2022

Reference Number: 6085276



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-NpjXdrbz4bvci>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #3 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Hallway #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

Compliant

📍 Location/Position: Living Room #1 (Level Ground)

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Switchboard (Smoke Alarm)

Compliant

📍 Location/Position: Entrance #1 (Level Ground)

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

Compliant

📍 Location/Position: Kitchen #1 (Level Ground)

Manufacturer: --Unknown--

1 photo are available to view online

Cord Guide

Compliant

📍 Location/Position: Living Room #1 (Level Ground)

Manufacturer: --Unknown--

1 photo are available to view online