



Service Report

Smoke Alarm Safety Service

Ref #: SR5824223

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au



Detector Inspector



Property Address

29 Meadows Boulevard , Strathpine QLD 4500

Generated On: 13:59:58 10/11/2021

Technician Name: Lachlan Joel Sushames

Date Performed: 09/11/2021

Reference Number: 5824223



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-TExl2rlbJaFaU>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Mains 240 Volt (9v battery) Smoke Alarm

✓ **Compliant**

📍 Location/Position: Bedroom #1 (Level Ground)

Expiry Year: 2027

1 photo are available to view online

Manufacturer: Clipsal

Mains 240 Volt (9v battery) Smoke Alarm

✓ **Compliant**

📍 Location/Position: Bedroom #2 (Level Ground)

Expiry Year: 2028

1 photo are available to view online

Manufacturer: Clipsal

Mains 240 Volt (9v battery) Smoke Alarm

✓ **Compliant**

📍 Location/Position: Corridor #1 (Level Ground)

Expiry Year: 2028

1 photo are available to view online

Manufacturer: Clipsal

Mains 240 Volt (9v battery) Smoke Alarm

✓ **Compliant**

📍 Location/Position: Hallway #1 (Level Ground)

Expiry Year: 2028

1 photo are available to view online

Manufacturer: Clipsal

Mains 240 Volt (9v battery) Smoke Alarm

✓ Compliant

📍 Location/Position: Bedroom #3 (Level Ground)

Expiry Year: 2028

1 photo are available to view online

Manufacturer: Clipsal

Mains 240 Volt (9v battery) Smoke Alarm

✓ Compliant

📍 Location/Position: Bedroom #4 (Level Ground)

Expiry Year: 2028

1 photo are available to view online

Manufacturer: Clipsal

Switchboard (Smoke Alarm)

✓ Compliant

📍 Location/Position: Garage #1 (Level Ground)

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

✓ Compliant

📍 Location/Position: Bedroom #1 (Level Ground)

Manufacturer: --Other--

1 photo are available to view online

Cord Guide

✓ Compliant

📍 Location/Position: Bedroom #2 (Level Ground)

Manufacturer: Detector Inspector

1 photo are available to view online

Cord Guide

✓ Compliant

📍 Location/Position: Living Room #1 (Level Ground)

Manufacturer: --Other--

1 photo are available to view online

Cord Guide

✓ Compliant

📍 Location/Position: Bedroom #3 (Level Ground)

Manufacturer: --Other--

1 photo are available to view online

Cord Guide

✓ Compliant

📍 Location/Position: Bedroom #4 (Level Ground)

Manufacturer: --Other--

1 photo are available to view online