



Service Report

Smoke Alarm Safety Service

Ref #: SR5969060

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

3/19 Daniells Street , Carina QLD 4152

Generated On: 13:43:43 07/02/2022

Technician Name: Jay McLaren

Date Performed: 04/02/2022

Reference Number: 5969060



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-Lkwju3tc31kBS>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Living Room #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Hallway #1 (Level Level 1)

Compliant

Expiry Year: 2031

Legislation
Check: 2

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Level 1)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Level 1)

Compliant

Expiry Year: 2031
Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #3 (Level Level 1)

Compliant

Expiry Year: 2031
Manufacturer: Detector Inspector

1 photo are available to view online

Switchboard (Smoke Alarm)

📍 Location/Position: Garage #1 (Level Ground)

Compliant

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

📍 Location/Position: Dining Room #1 (Level Ground)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Living Room #1 (Level Ground)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Bedroom #1 (Level Level 1)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Bedroom #2 (Level Level 1)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Bedroom #3 (Level Level 1)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Entrance #1 (Level Ground)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Laundry #1 (Level Ground)

Compliant

1 photo are available to view online