



Service Report

Smoke Alarm Safety Service

Ref #: SR6044833

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au



Detector Inspector



Property Address

3/99 Wallace Street , Chermside QLD 4032

Generated On: 17:33:50 23/03/2022

Technician Name: Alan Dodds

Date Performed: 21/03/2022

Reference Number: 6044833

License No.: C 6331



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-7fSofWMo8oZzz>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Level 1)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #3 (Level Level 1)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Level 1)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Kitchen #1 (Level Ground)

Compliant

Expiry Year: 2031

Expiry Year: 2031
Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

Compliant

📍 Location/Position: Hallway #1 (Level Level 1)

Expiry Year: 2031
Manufacturer: Detector Inspector

1 photo are available to view online

Switchboard (Smoke Alarm)

Compliant

📍 Location/Position: Garage #1 (Level Ground)

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

Compliant

📍 Location/Position: Living Room #1 (Level Ground)

1 photo are available to view online

Cord Guide

Compliant

📍 Location/Position: Living Room #1 (Level Ground)

1 photo are available to view online

Cord Guide

Compliant

📍 Location/Position: Bedroom #2 (Level Level 1)

1 photo are available to view online

Cord Guide

📍 Location/Position: Bedroom #1 (Level Level 1)

Compliant

1 photo are available to view online

Cord Guide

📍 Location/Position: Bedroom #3 (Level Level 1)

Compliant

1 photo are available to view online