





Property Address

1/10 Bellthorpe Circle, Kallangur QLD 4503



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

Reference Number: 5676022

Technician Name: Ivan Sionemale **Date Performed**: 24/08/2021

Generated On: 00:23:51 25/08/2021

Click Here to View Full Report with Photos

Alternatively, use this link: https://detc.in/service-reports-7UCAVocRnRwxr

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.



✓ Compliant

Mains 240 Volt 10Yr Lithium Smoke Alarm

✓ Location/Position: Living Room #1 (Level Ground)

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

✓ Location/Position: Hallway #1 (Level Level 1)

Expiry Year: 2030

Manufacturer: Detector Inspector

✓ Compliant

Detachable 10 Year Lithium Smoke Alarm

✓ Location/Position: Bedroom #1 (Level Level 1)

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

✓ Location/Position: Bedroom #2 (Level Level 1)

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

✓ Compliant

Compliant

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

✓ Location/Position: Hallway #2 (Level Level 1)

1 photo are available to view online

✓ Compliant

✓ Compliant

✓ Compliant

Manufacturer: Detector Inspector

2030

Expiry Year:

Detachable 10 Year Lithium Smoke Alarm

◀ Location/Position:Bedroom #3 (Level Level 1)

Expiry Year: 2030 1 photo are available to view online

Manufacturer: Detector Inspector

Switchboard (Smoke Alarm)

 ✓ Location/Position: Garage #1 (Level Ground)

1 photo are available to view online