



Service Report

Smoke Alarm Safety Service

Ref #: SR6418734

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au



Detector Inspector



Property Address

2/10 Bellthorpe Circle , Kallangur QLD 4503

Generated On: 18:42:54 25/08/2022

Technician Name: Ben Carroll

Date Performed: 25/08/2022

Reference Number: 6418734

Supervisor: James (Lee) Muncey

Supervisor Licence No.: -



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-vg3wgidwfcHsw>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Bedroom #1 (Level Level 1)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Bedroom #2 (Level Level 1)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 **Location/Position:** Hallway #1 (Level Level 1)

Compliant

Expiry Year: 2030

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 **Location/Position:** Living Room #1 (Level Level 1)

Compliant

Expiry Year: 2030
Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Entrance #1 (Level Ground)

Compliant

Expiry Year: 2030
Manufacturer: Detector Inspector

1 photo are available to view online