



Property Address

1209/855 Stanley Street , Woolloongabba QLD 4102

Generated On: 11:07:25 07/03/2022

Technician Name: Sarah Buckley

Date Performed: 04/03/2022

Reference Number: 6031796



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-ZEMNeL49xg7wE>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Hallway #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Cordless Window Covering Service

There are no outstanding safety concerns or compliance items related to the cordless window coverings at this property.

✓ **Compliant**

Cord Guide

📍 Location/Position: Living Room #1 (Level Ground)

Compliant

1 photo are available to view online

Cord Guide

 Location/Position: Bedroom #1 (Level Ground)

Compliant

1 photo are available to view online