



Service Report

Smoke Alarm Safety Service

Ref #: SR5982009

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

4/47 Glasgow Street , Zillmere QLD 4034

Generated On: 05:21:16 11/02/2022

Technician Name: Armand Sarmiento

Date Performed: 10/02/2022

Reference Number: 5982009



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-o0vrrbPEPLxGR>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Dining Room #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 Location/Position: Living Room #1 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Detector Inspector

1 photo are available to view online

Switchboard (Smoke Alarm)

📍 Location/Position: Living Room #1 (Level Ground)

Compliant