



# Service Report

## Smoke Alarm Safety Service

Ref #: SR6312909

Detector Inspector (QLD) Pty Ltd  
ABN 27 628 528 772  
www.detectorinspector.com.au

G+ in f y



Detector Inspector



### Property Address

1/8 Thistle Street , Upper Caboolture QLD 4510



### Real Estate Agency

Image Property



### Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

**Generated On:** 18:24:36 19/07/2022

**Technician Name:** Ivan Sionemale

**Date Performed:** 19/07/2022

**Reference Number:** 6312909

**Supervisor:** James (Lee) Muncey

**Supervisor Licence No.:** -

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:  
<https://detc.in/service-reports-o8fHvobIG3XqE>

## Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

### Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Bedroom #1 (Level Ground)

**Compliant**

**Expiry Year:** 2031

**Manufacturer:** Detector Inspector

1 photo are available to view online

### Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Bedroom #2 (Level Ground)

**Compliant**

**Expiry Year:** 2031

**Manufacturer:** Detector Inspector

1 photo are available to view online

### Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Bedroom #3 (Level Ground)

**Compliant**

**Expiry Year:** 2031

**Manufacturer:** Detector Inspector

1 photo are available to view online

### Mains 240 Volt 10Yr Lithium Smoke Alarm

📍 **Location/Position:** Hallway #1 (Level Ground)

**Compliant**

Expiry Year: 2030  
Manufacturer: Detector Inspector

1 photo are available to view online

Switchboard (Smoke Alarm)

 Location/Position: Garage #1 (Level Ground)

Compliant