

G+

in f 🗈

Property Address	Generated On	02:53:36 22/02/202
25 Kingsdale Avenue , Thornlands QLD 4164	Technician Name:	
	Date Performed:	
Real Estate Agency	Reference Number:	
Image Property	License No.:	
Current Legislation		
(Upgraded 2022) Fire and Emergency Services Act	Click Here to View Full Report with Photos	
	Alte https://detc.in/service-re	ernatively, use this linl eports-1nXihLZdyXUs
noke Alarm Safety Service		
ere are no outstanding safety concerns or compliance items related to the noke alarms at this property.		Compliant
Mains 240 Volt 10Yr Lithium Smoke Alarm		Compliant
Mains 240 Volt 10Yr Lithium Smoke Alarm ✓ Location/Position: Kitchen #1 (Level Ground)	1 Pro	Compliant
		oblem Resolved 오
Location/Position: Kitchen #1 (Level Ground)		
 Location/Position: Kitchen #1 (Level Ground) Expiry Year: 2030 	1 photo are ava	oblem Resolved 오
 Location/Position: Kitchen #1 (Level Ground) Expiry Year: 2030 Manufacturer: Legrand 	1 photo are ava	oblem Resolved
 Location/Position: Kitchen #1 (Level Ground) Expiry Year: 2030 Manufacturer: Legrand List Of Problem(s) Found 	1 photo are ava <u>Es</u> t	oblem Resolved 오
 Location/Position: Kitchen #1 (Level Ground) Expiry Year: 2030 Manuf acturer: Legrand List Of Problem(s) Found Source Mains detected within Property Replace Mains Powered Smoke Alarm with Compatible Interconnect 	1 photo are ava <u>Es</u> t	oblem Resolved ©
 Location/Position: Kitchen #1 (Level Ground) Expiry Year: 2030 Manufacturer: Legrand List Of Problem(s) Found Mismatched Smoke alarms detected within Property Replace Mains Powered Smoke Alarm with Compatible Interconnec 240V Smoke Alarm 	1 photo are ava <u>Es</u> t	oblem Resolved ©



1 Problem Resolved 🤗

Expiry Year: 2030 Manufacturer: Legrand


1 photo are available to view online

List Of Problem(s) Found


Escalation Category

Compliant



















Manufacturer: -- Other--

1 photo are available to view online