



Service Report

Smoke Alarm Safety Service

Ref #: SR6476563

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

2/51 Rennie Street , Indooroopilly QLD 4068

Generated On: 01:52:50 15/09/2022

Technician Name: Muhammad Khizzar

Date Performed: 12/09/2022

Reference Number: 6476563

Supervisor: Keith Whelton

Supervisor Licence No.: -



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-ABv2vGL28onEL>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #1 (Level Level 1)

Compliant

Expiry Year: 2027

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Brooks

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #2 (Level Level 1)

Compliant

Expiry Year: 2030

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Brooks

Detachable 10 Year Lithium Smoke Alarm

📍 Location/Position: Bedroom #3 (Level Level 1)

Compliant

Expiry Year: 2029

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Brooks

Mains 240 Volt (9v battery) Smoke Alarm

Compliant

📍 Location/Position: Entrance #1 (Level Ground)

Expiry Year: 2031

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Brooks

Mains 240 Volt (9v battery) Smoke Alarm

Compliant

📍 Location/Position: Hallway #1 (Level Level 1)

Expiry Year: 2031

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Brooks

Switchboard (Smoke Alarm)

Compliant

📍 Location/Position: Garage #1 (Level Ground)

1 photo are available to view online

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ Compliant

Cord Guide

Compliant

📍 Location/Position: Bedroom #4 (Level Level 1)

Manufacturer: -- Other --

1 photo are available to view online