Service Report Smoke Alarm Safety Service Ref #: SR6365479

Detector Inspector (QLD) Pty Ltd ABN 27 628 528 772 www.detectorinspector.com.au

in f





Property Address

404/24 Bromley Street , Kangaroo Point QLD 4169



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

Generated On: 12:09:34 20/07/2022

Technician Name: Franco Migliorini

Date Performed: 19/07/2022

Reference Number: 6365479

Licence No.: 124590

Supervisor: Joel Ashdown

Supervisor Licence No.: -



Click Here to View Full Report with Photos

Alternatively, use this link: https://detc.in/service-reports-h1nc84srLk3Uq

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.



Detachable 10 Year Lithium Smoke Alarm

▼ Location/Position: Bedroom #1 (Level Ground)

Compliant

Expiry Year: 2029 Manufacturer: Brooks

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

▼ Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2029 Manufacturer: Brooks

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

▼ Location/Position: Hallway #1 (Level Ground)

Compliant

Expiry Year: 2029 Manufacturer: Brooks

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

▼ Location/Position: Living Room #1 (Level Ground)

Compliant

Expiry Year: 2029 Manufacturer: Brooks

1 photo are available to view online

Switchboard (Smoke Alarm)

▼ Location/Position: Living Room #1 (Level Ground)

Compliant