



Service Report

Smoke Alarm Safety Service

Ref #: SR6417009

Detector Inspector (QLD) Pty Ltd
ABN 27 628 528 772
www.detectorinspector.com.au

G+ in f y



Detector Inspector



Property Address

8/12 Bailey Street , New Farm QLD 4005

Generated On: 12:25:56 11/08/2022

Technician Name: Hayden Taylor (E) (PINK)

Date Performed: 09/08/2022

Reference Number: 6417009

Supervisor: Mason Clarke

Supervisor Licence No.: -



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

[Click Here to View Full Report with Photos](#)

Alternatively, use this link:
<https://detc.in/service-reports-LTMFbLc8uaNUy>

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.

✓ **Compliant**

Detachable 10 Year Lithium Smoke Alarm

📍 **Location/Position:** Kitchen #1 (Level Ground)

Compliant

Expiry Year: 2031

1 photo are available to view online

Legislation
Check: 2

Manufacturer: Detector Inspector

Switchboard (Smoke Alarm)

📍 **Location/Position:** Rear of house #1 (Level Ground)

Compliant

Corded Window Covering Service

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.

✓ **Compliant**

Cord Guide

📍 **Location/Position:** Kitchen #1 (Level Ground)

Compliant

Manufacturer: --Other--

1 photo are available to view online

Cord Guide

 Location/Position: Living Room #1 (Level Ground)

Compliant

Manufacturer: --Other--

1 photo are available to view online

Cord Guide

 Location/Position: Living Room #1 (Level Ground)

Compliant

Manufacturer: --Other--

1 photo are available to view online