# Service Report Smoke Alarm Safety Service Ref #: SR6118201

Detector Inspector (QLD) Pty Ltd ABN 27 628 528 772 www.detectorinspector.com.au

· in f 🗳





#### **Property Address**

3/108 Ryans Road, Nundah QLD 4012



# **Real Estate Agency**

Image Property



# **Current Legislation**

(Upgraded 2022) Fire and Emergency Services Act

Generated On: 12:42:00 30/03/2022

Technician Name: Ivan Sionemale

Date Performed: 28/03/2022
Reference Number: 6118201

**a** (

Click Here to View Full Report with Photos

Alternatively, use this link: https://detc.in/service-reports-071arRLjrttnU

# **Smoke Alarm Safety Service**

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.



#### Detachable 10 Year Lithium Smoke Alarm

✓ Location/Position: Living Room #1 (Level Ground)

Expiry Year: 2031

Manufacturer: Emerald Planet

1 photo are available to view online

#### Detachable 10 Year Lithium Smoke Alarm

**▼** Location/Position: Bedroom #1 (Level Ground)

Compliant

Compliant

Expiry Year: 2031

Manufacturer: Emerald Planet

1 photo are available to view online

# Detachable 10 Year Lithium Smoke Alarm

**▼** Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2031

Manufacturer: Emerald Planet

1 photo are available to view online

### **Corded Window Covering Service**

There are no outstanding safety concerns or compliance items related to the corded window coverings at this property.



# **Cord Guide**

**▼** Location/Position: Dining Room #1 (Level Ground)

Compliant

Manufacturer: --Other--

1 photo are available to view online