

Compliance Report

Property Address: Unit 25, 6 Jorl Street, Buderim

Inspected by: Daniel Young

Inspection Date: 20/06/2024

Page: 1 of 1

Smoke Alarms

At this inspection the following alarm/s were present:

Type	Expiry	Alarm Position
Clipsal 230v	04/2030	Main bedroom
Clipsal 230v	05/2030	Bed 2
Clipsal 230v	05/2030	Hall / top of stairs
Clipsal 230v	05/2030	Bottom of stairs

THIS PROPERTY IS COMPLIANT.

On the date that this property was inspected, the smoke alarm/s met the requirements of the Australian Standard 3786-1993, and the relevant sections of the Building Code of Australia. The property only remains compliant until the next tenancy change or tenancy renewal, at which time the property must be re-inspected.