

### STATEMENT OF **COMPLIANCE**

#### **PROPERTY**

26/390 Simpsons Road Bardon QLD, 4065

#### TYPE OF VISIT

Lease Renewal

#### **SMOKE ALARM STATUS**

**⊘Currently Compliant** 

#### **INSPECTION DATE**

18/09/2024

#### Compliance Notes:

No notes available.

#### **SMOKE ALARMS (INTERCONNECTED) SUMMARY**

#### **ALARM 1 - ENTRY**

POWER: 240v

TYPE: MAKE: P/E Interconnected

MODEL:

**DETECTOR INSPECTOR** 

**EXPIRY:** 

DI240I 2030

DB:

89

**REASON:** N/A





#### ALARM 2 - BED1

POWER: 3vLi

TYPE: MAKE:

P/E Interconnected

MODEL:

**DETECTOR INSPECTOR** 

**EXPIRY:** 


DI10YLI 2029

89

DB:

**REASON:** 

N/A





All smoke alarms located within the property as detailed above have been cleaned and tested as per manufacturers instructions and been installed in accordance with Standard AS 3786 (2014) Smoke Alarms, Building Code of , Volume 2 Part 3.7.2 of the National Construction code series (BCA) and AS/NZS 3000:2018 Electrical installations.

Where alarm Power is 240v or 240vLi the alarm is mains powered. (Hard Wired). All other alarms are battery powered.

\* Not required for compliance



1300 41 66 67

PO Box 6393 Yatala DC QLD 4207 ABN: 28 132 807 491 e: info@sats.com.au

Electrical Licenses: (NSW) 264079C | (ACT) 2014969 | (SA) PGE 332279 | (QLD) 92156





# SAFETY SWITCH REPORT

#### SAFETY SWITCH TEST SUMMARY

#### SWITCH 1 - ENTRY CUPBOARD

EXISTING

MAKE: HAGER MODEL: C10 RESULT: PASS



#### SWITCH 2 - ENTRY CUPBOARD

EXISTING

MAKE: HAGER MODEL: C20 RESULT: PASS



#### SWITCH 3 - ENTRY CUPBOARD

EXISTING

MAKE: HAGER MODEL: C20 RESULT: PASS



#### SWITCH 4 - ENTRY CUPBOARD

XISTING

MAKE: HAGER MODEL: C25 RESULT: PASS



#### SWITCH 5 - ENTRY CUPBOARD

EXISTING

MAKE: HAGER MODEL: C20 RESULT: PASS



#### 5 Safety Switches Present

The safety switches at 26/390 Simpsons Road, Bardon have been tested and passed a basic mechanical test at the time of inspection. The test determined that the switches were in working order but no test has been performed to determine the speed at which the device activated. As a result of variables beyond the control of SATS, the results of the test may change in the future. SATS is not responsible for any costs incurred due to failed tests or any costs incurred to replace the failed device.

### **Smoke Alarm Testing Services Pty Ltd.**

1300 41 66 67

PO Box 6393 Yatala DC QLD 4207 ABN: 28 132 807 491 e: info@sats.com.au Electrical Licenses: (NSW) 264079C | (ACT) 2014969 | (SA) PGE 332279 | (QLD) 92156



## CORDED WINDOWS REPORT

#### **CORDED WINDOWS SUMMARY**

**Room 1 - LIVING** 

EXISTING

NUMBER OF CORDED WINDOWS: 4

Room 2 - BED1

EXISTING

NUMBER OF CORDED WINDOWS: 1

All Corded Windows within the Property as detailed above are Compliant with Current Legislation and Australian Standards. The Required Clips and Tags have been installed to ensure proper compliance with Current Legislation. Further data is available on the agency portal