Service Report Smoke Alarm Safety Service Ref #: SR6459399

Detector Inspector (QLD) Pty Ltd ABN 27 628 528 772 www.detectorinspector.com.au





Property Address

13/35 Maher Street, Zillmere QLD 4034



Real Estate Agency

Image Property



Current Legislation

(Upgraded 2022) Fire and Emergency Services Act

Generated On: 20:57:33 15/09/2022

Technician Name: Ivan Sionemale Date Performed: 14/09/2022 Reference Number: 6459399

Supervisor: Joel Ashdown

Supervisor Licence No.: -



Click Here to View Full Report with Photos

Alternatively, use this link: https://detc.in/service-reports-CeM4ieCYAtzEn

Smoke Alarm Safety Service

There are no outstanding safety concerns or compliance items related to the smoke alarms at this property.



Compliant

Detachable 10 Year Lithium Smoke Alarm

▼ Location/Position: Bedroom #1 (Level Ground)

Expiry Year: 2031

Legislation

Check:

2

Manufacturer: Detector Inspector

1 photo are available to view online

Detachable 10 Year Lithium Smoke Alarm

▼ Location/Position: Bedroom #2 (Level Ground)

Compliant

Expiry Year: 2031

Legislation

Check:

2

Manufacturer: Detector Inspector

1 photo are available to view online

Mains 240 Volt 10Yr Lithium Smoke Alarm

▼ Location/Position: Living Room #1 (Level Ground)

Compliant

Expiry Year:

2031

Legislation Check:

Manufacturer: Detector Inspector

1 photo are available to view online

Safety Switch (RCD)

▼ Location/Position: Bedroom #3 (Level Ground)

Compliant

Manufacturer: Hager

Switchboard (Smoke Alarm)

▼ Location/Position: Bedroom #3 (Level Ground)

Compliant

1 photo are available to view online

Switchboard (Smoke Alarm)

▼ Location/Position: Bedroom #3 (Level Ground)

Compliant

1 photo are available to view online

Switchboard (Smoke Alarm)

▼ Location/Position: Bedroom #3 (Level Ground)

Compliant

1 photo are available to view online

Switchboard (Smoke Alarm)

▼ Location/Position: Bedroom #3 (Level Ground)

Compliant

1 photo are available to view online