

PROPERTY MANAGEMENT SUPPORT

with a difference.

## **SITE ADDRESS**

46 Morna St Newport QLD 4020

## COMPLIANCE CERTIFICATE

**INSPECTION DATE** 

09 Apr 2025

**COMPLIANCE STATUS** 





SMOKE ALARMS

Level 1 Entry

SAFETY SWITCHES

Jun 2029

SMOKE ALARMS ALARM POSITION EXPIRY

1: Clipsal Cable Interconnect 240V Photoelectric Smoke alarm compliant.










Level 2 Bed 2 Jun 2029



SMOKE ALARMS ALARM POSITION EXPIRY

3: Clipsal Cable Interconnect 240V Photoelectric Smoke alarm compliant.







4: Clipsal Cable Interconnect 240V Photoelectric Smoke alarm compliant.


Level 2 Bed 4 Jun 2029





5: Clipsal Cable Interconnect 240V Photoelectric **Smoke alarm compliant.** 

Level 2 Master Bedroom Jun 2029





SMOKE ALARMS ALARM POSITION EXPIRY

6: Clipsal Cable Interconnect 240V Photoelectric Smoke alarm compliant.









7: Clipsal Cable Interconnect 240V Photoelectric Smoke alarm compliant.

Level 2 Rear Hall Jun 2029





8: Clipsal Cable Interconnect 240V Photoelectric This smoke alarm is not required for compliance.

Level 2 Top Of Stairs Jun 2029





## **SAFETY SWITCHES**

1: 1 Pole 20A × 1

2: 1 Pole 10A × 2

3: 1 Pole 32A × 1



## **STATUS**

Safety switch compliant.

Safety switch compliant.

Safety switch compliant.

**DISCLAIMER:** At the time this property was inspected, the smoke alarms met the requirements of Australian Standard 3786-2014 and the relevant sections of the Building Code of Australia, as required by the Queensland Fire and Emergency Services Act 1990 Division 5A and Fire and Emergency Services (Domestic Smoke Alarms) Amendment Bill 2016.

The property needs to be re-inspected within 30 days before any tenancy change or tenancy renewal, at which time this certificate will not be valid.



