



Certificate of Testing and Compliance

As per Electrical Safety Regulations 2013

*** Work Performed for:**

*** Company Name:**

*** Persons Name:** Kirsty Lindner

*** Site Address:** 97-111 Wearing Rd, North Maclean

*** Electrical Installation / Equipment Tested:**

(What has been tested and what did it entail)

Dig down beside property pole W17228A
400mm wide by 300mm deep to
inspect integrity of the pole.

*** Electrical Contractors Details:**

Name: Rylec (Qld) Pty Ltd

*** Contractor's Licence Number:** 77297

Phone Number: 07 5541 2285

*** Date testing was undertaken:** 24/7/2025

This certifies that the electrical installation or equipment, to the extent it is affected by the electrical work, has been tested to ensure that it is electrically safe and is in accordance with the requirements of the wiring rules and any other standards applying under the Electrical Safety Regulations 2013 to the electrical installation.

*** Electrical Workers Details**

*** Name:** Steven Ryan

*** Licence Number:** 119512

*** Signature:** 

*** Date:**